From: Richard Rupert/R3/USEPA/US

Sent: 2/3/2012 8:25:45 PM

To: "richard.fetzer@epa.gov" <richard.fetzer@epa.gov>

CC:

Subject: Fw: Cabot QA/QC

I haven't look at the attached documents yet but, figured I would pass them on to you asap.

Richard Rupert
On-Scene Coordinator
U.S.EPA
1650 Arch Street - 3HS31
Philadelphia, PA 19103
(215) 814-3463 - office
215 514 8773 - MOBILE
rupert.richard@epa.gov
----- Forwarded by Richard Rupert/R3/USEPA/US on 02/03/2012 08:24 PM -----

From: Terry Simpson/ESC/R3/USEPA/US
To: Rupert.Richard@epamail.epa.gov

Date: 02/03/2012 03:39 PM Subject: Fw: Cabot QA/QC

Hi, Rich --

Karen Johnson suggested that you'd be the POC for the existing Cabot data. As my email to Karen explains (scroll way down), we are doing an inventory of the QC data for each of the analytical data files provided by Cabot and providing a recommendation on the use of that data. Given that most of the data files do not contain enough QC data to perform validation, this was the best we could do for now. If you'd like to have it all validated, the checklists are designed to inform which data is needed.

If you could take a look at the attached files to let me know if this is will be useful, I'd really appreciate it. Thanks!

Terry

Terry Simpson, Regional QA Manager

US EPA Region 3

Environmental Science Center

701 Mapes Road

Ft. Meade, MD 20755-5350

Voice: 410.305.2739 Fax: 410.305.3095

email: simpson.terry@epa.gov

Region 3 QA Website:

http://www.epa.gov/region03/esc/qa/index.htm

DIM0120938 DIM0120938

Only four types of organizations need to worry about data quality:

Those that care about their customers, Those that care about profit and loss, Those that care about their employees, and Those that care about their futures.

- Thomas C. Redman (2006)

---- Forwarded by Terry Simpson/ESC/R3/USEPA/US on 02/03/2012 03:29 PM -----

From: KarenD Johnson/R3/USEPA/US

To: Terry Simpson/ESC/R3/USEPA/US@EPA

 Date:
 02/03/2012 10:15 AM

 Subject:
 Re: Fw: Cabot QA/QC

Thanks Terry- but I think Rich Rupert is going to be the one who needs this most, I'm going to forward your previous info to him for use with the data spread sheet they are populating including data quality. Thanks for all your work on this!!! Karen D. Johnson, Chief

Ground Water & Enforcement Branch

From: Terry Simpson/ESC/R3/USEPA/US
To: KarenD Johnson/R3/USEPA/US@EPA

Cc: Cynthia Metzger/ESC/R3/USEPA/US@EPA, Fred Foreman/ESC/R3/USEPA/US@EPA, Cynthia Caporale/ESC/R3/USEPA/US@EPA

Date: 02/03/2012 08:58 AM Subject: Fw: Cabot QA/QC

Hi, Karen --

I should have been clearer about this in my message. This is not our final analysis. I am still populating the limitations table, but I just wanted to check in as to whether this is what you are looking for.

Terry

Terry Simpson, Regional QA Manager US EPA Region 3 Environmental Science Center 701 Mapes Road Ft. Meade, MD 20755-5350

Voice: 410.305.2739 Fax: 410.305.3095

email: simpson.terry@epa.gov

Region 3 QA Website:

http://www.epa.gov/region03/esc/qa/index.htm

Only four types of organizations need to worry about data quality:

Those that care about their customers, Those that care about profit and loss, Those that care about their employees, and Those that care about their futures.

- Thomas C. Redman (2006)

DIM0120938 DIM0120939

---- Forwarded by Terry Simpson/ESC/R3/USEPA/US on 02/03/2012 08:55 AM -----

From: Terry Simpson/ESC/R3/USEPA/US
To: KarenD Johnson/R3/USEPA/US@EPA

Cc: Cynthia Metzger/ESC/R3/USEPA/US@EPA, Fred Foreman/ESC/R3/USEPA/US@EPA

Date: 02/02/2012 06:16 PM

Subject: Cabot QA/QC

Hi, Karen --

Just wanted to update you on Ft. Meade's QA/QC review of the existing data from Cabot's initial 104e response. I'm attaching a table and two checklists. We are using the checklists to inventory the amount of QC in each data file. This will serve two purposes: 1) to make a determination whether there is enough QC present to validate the data; and 2) to document exactly which QC information is missing and/or needed, should we want to specifically request it from Cabot and their labs. The table documents each file by report title, date, and analyses. It also provides a recommendation on the limited use of the data and cross-references the affected samples.

[attachment "QA_QC Review of Cabot provided data 03Feb2012.docx" deleted by Terry Simpson/ESC/R3/USEPA/US] [attachment "Inorganic_Inventory of QC Measures.docx" deleted by Terry Simpson/ESC/R3/USEPA/US] [attachment "Organic_Inventory of QC Measures.docx" deleted by Terry Simpson/ESC/R3/USEPA/US]

Please take a look at these and let me know your thoughts. Is there anything that you were expecting to see that isn't in here? Thanks!

Terry

Terry Simpson, Regional QA Manager US EPA Region 3 Environmental Science Center 701 Mapes Road Ft. Meade, MD 20755-5350

Voice: 410.305.2739 Fax: 410.305.3095

email: simpson.terry@epa.gov

Region 3 QA Website:

http://www.epa.gov/region03/esc/qa/index.htm

Only four types of organizations need to worry about data quality:

Those that care about their customers, Those that care about profit and loss, Those that care about their employees, and Those that care about their futures.

- Thomas C. Redman (2006)

DIM0120938 DIM0120940